



	אוט	KOITI	pak	
1. 2. 3. 4. 5. 6. 7. 8. 9. 10. 11. 12. 13. 14. 15. 16. 17.	200X500	1	1	
2.	2000X500	1	1 1 2 2/3 2 2 3 3 1 1 4 4 5 5	
3.	1882X495 1882X495	1	1	
4.	1882X495	1	1	
5.	1764X495	1	2	
6.	864X495	1	2	
7.	432X495	2	2/3	
8.	1351X530	1	2	
9.	100X1764	2	2	
10.	863X495	1	3	
11.	430X480	5	3	
12.	1910X440	2	1	
13.	1910X450	2	1	
14.	1476X446	1	4	
15.	1476X446	1	4	
16.	1896X446	1	5	
17.	1896X446	1	5	
18.	896X206	1 2 1 2 1 5 2 2 1 1 1 1 2 2 2	6 6	
19.	832X449	2	6	
20.	832X134	2	6	

Ø 10x35	9	3,5x16		3x20		4x25		4x40	
	36X 06370		72X 01231		16X 00230		16X 13995		4X 14001
6,3x13	3	7x50		4					
	20X 14425		28X 00161	U	1X 00160	9 2	24X 00182		06155
OR.	9		A		12X	(g	
	4X 00694	2	150X 10109		12X 11373 11374		6X 00359		4X 08579
	•			L-96		L-128		L-856	
	12X 09936		12X 09936	U	4X 00265		4X 00267		1X 00226
L-1864		L-450/H1	50					L-424	
	1X 00819		2X 20089		2X 23102		12X 03291		1X 00690